



# ***PRODUCTS APPLICATION LISTS***

EXAMPLE OF THE SYMBOLS INDICATING  
THE CAR YEAR OF MANUFACTURE  
( >98 = from 1998 ) ( <96 = up to 1996 )  
( >99<00 = from 1999 up to 2000 )

## **OMP racing s.r.l.**

via E. Bazzano, 5 16019 Ronco Scrivia (Genova) Italy

**phone:** (+39)01096501 **fax:** (+39)010935698

### **EXPORT DEPARTMENT:**

**phone:** (+39)0109650150 **fax:** (+39)010935698

**www.ompracing.it** - **e-mail:** omp.info@ompracing.it

## **OMP SHOW ROOM AND POINT OF SALE IN GENOVA**

via E. Bazzano, 5 16019 Ronco Scrivia (Genova) Italy

**phone:** (+39)0109650140 **fax:** (+39)0109350580

**timetable:** Monday-Friday: 9-12.30 14-17.15 Saturday: closed

*Motorway A7 MI-GE, exit Ronco Scrivia*

## **OMP POINT OF SALE IN MILANO**

via Don Minzoni 16/18 20090 Buccinasco (Milano)

**phone:** (+39)0245700774 **fax:** (+39)0245700833

**timetable:** Monday: 15-19 Tuesday-Friday: 9-12.30 15-19

Saturday: 9-12.30

*Motorway Ovest Milano, exit Porta Genova*

## **OMP AMERICA LLC**

7056 Portal Way Building I, Unit 1 Ferndale, WA 98248 USA

**phone:** (+1) 360.366.0959 **fax:** (+1) 360.366.0590

**Toll free number:** 1 866 667-2637

**www.ompamerica.com** - **e-mail:** info@ompamerica.com

# ADAPTORS FOR SEAT FIXING BRACKETS

Seats with lower fixing points require the use of sliding brackets HC/665.

(\*) not suitable for side fixing seats

CAR	REF.	CAR	REF.	CAR	REF.	CAR	REF.
<b>ALFA ROMEO</b>		<b>FIESTA 2<sup>nd</sup> series &gt;89&lt;94</b>		<b>OPEL</b>		<b>SUBARU</b>	
146	seat (right) HC/790/D seat (left) HC/790/S	<b>PUMA/FIESTA 3<sup>rd</sup> series &gt;94</b>		<b>CORSA 2<sup>nd</sup> series &gt;93</b>		<b>IMPREZA &gt;12/00</b>	
147	seat (right) HC/797/D seat (left) HC/797/S	seat (right) HC/793/D seat (left) HC/793/S		seat (right) * HC/785/D seat (left) * HC/785/S		seat (right) HC/813/D seat (left) HC/813/S	
155	HC/740	<b>FIESTA 4<sup>th</sup> series &gt;05/02</b>		<b>CORSA 3<sup>rd</sup> series &gt;10/00</b>		<b>IMPREZA &gt;12/00</b>	
156	seat (right) HC/789/D seat (left) HC/789/S	seat (right) HC/845/D seat (left) HC/845/S		seat (right) HC/841/D seat (left) HC/841/S		requires welding seat (right) HC/825/D seat (left) HC/825/D	
GTV >97	HC/782	<b>ESCORT/SIERRA Cosworth</b>		<b>KADETT E</b>		<b>SUZUKI</b>	
<b>AUDI</b>		seat (right) HC/778/D seat (left) HC/778/S		seat (right) HC/737/D seat (left) HC/737/S		<b>SWIFT &gt;05/05</b>	
A3 >96<03	seat (right) HC/780/D seat (left) HC/780/S	<b>FOCUS 3 doors</b>		<b>ASTRA 1<sup>st</sup> series</b>		seat (right) HC/851/D seat (left) HC/851/S	
>03	seat (right) HC/838/D seat (left) HC/838/S	seat (right) HC/816/D seat (left) HC/816/S		seat (right) HC/737/D seat (left) HC/737/S		<b>TOYOTA</b>	
TT >11/98	HC/817	<b>MUSTANG &gt;78&lt;98</b>		<b>ASTRA 2<sup>nd</sup> series &gt;98</b>		<b>YARIS 1.0 &gt;04/99</b>	
<b>BMW</b>		HC/853		HC/804		seat (right) HC/799/D seat (left) HC/799/S	
SERIES 1 E87 >09/04	HC/848	<b>HYUNDAI</b>		<b>PEUGEOT</b>		seat (right) HC/788/D seat (left) HC/788/S	
SERIES 3 E30/E36	HC/772	<b>COUPÉ &gt;02</b>		106 seat (right) HC/781/D seat (left) HC/781/S		<b>COROLLA</b>	
SERIES 3 E46 all models incl. M3	HC/798	seat (right/left) HC/819		205 HC/735 206 HC/795		seat (right) HC/788/D seat (left) HC/788/S	
<b>CITROEN</b>		<b>HONDA</b>		306 seat (right) HC/784/D seat (left) HC/784/S		<b>CELICA &gt;11/99</b>	
SAXO	seat (right) HC/781/D seat (left) HC/781/S	<b>CIVIC V-Tec R-Type 3 doors &gt;09/01</b>		309 HC/777		seat (right) HC/821/D seat (left) HC/821/S	
C3/C2	seat (right) HC/834/D seat (left) HC/834/S	seat (right) HC/815/D seat (left) HC/815/S		<b>PORSCHE</b>		<b>CELICA GT &lt;11/99</b>	
<b>DAEWOO</b>		<b>INTEGRA</b>		911/996/997 GT3 HC/854		seat (right) HC/783/D seat (left) HC/783/S	
LANOS	seat (right) HC/791/D seat (left) HC/791/S	seat (right) HC/792/D seat (left) HC/792/S		only for side fixing seats		<b>LAND CRUISER &gt;02</b>	
<b>FERRARI</b>		<b>LANCIA</b>		<b>RENAULT</b>		seat (right) HC/855/D seat (left) HC/855/S	
348/355	HC/806	<b>DELTA 1<sup>st</sup> series 2.0 Integrale</b>		R5 HC/666		<b>VOLKSWAGEN</b>	
360 MODENA	HC/807	HC/773		<b>CLIO 1<sup>st</sup>/2<sup>nd</sup> series</b>		<b>LUPO &gt;98</b>	
<b>FIAT</b>		<b>MAZDA</b>		seat (right) HC/779/D seat (left) HC/779/S		seat (right) HC/780/D seat (left) HC/780/S	
CINQUECENTO/SEICENTO	HC/796	<b>MX5</b>		<b>MEGANE</b>		<b>POLO 1<sup>st</sup> series 10/81&lt;11/94</b>	
UNO	HC/739	3 >03 seat (right) HC/835/D seat (left) HC/835/S		seat (right) HC/742/D seat (left) HC/742/S		HC/738	
PUNTO 1 <sup>st</sup> series	seat (right) HC/786/D seat (left) HC/786/S	<b>MG</b>		<b>ROVER</b>		<b>POLO 2<sup>nd</sup> series &gt;11/94</b>	
PUNTO 2 <sup>nd</sup> series >99	seat (right) HC/797/D seat (left) HC/797/S	ZR >01 seat (right) HC/846/D seat (left) HC/846/S		25/200 >96 seat (right) HC/846/D seat (left) HC/846/S		seat (right) HC/780/D seat (left) HC/780/S	
TIPO	HC/740	<b>MINI</b>		<b>SEAT</b>		<b>POLO 4<sup>th</sup> series &gt;02</b>	
STILO >01	seat (right) HC/811/D seat (left) HC/811/S	<b>ONE &gt;09/01</b>		<b>IBIZA 2<sup>nd</sup> series &gt;93</b>		seat (right) HC/814/D seat (left) HC/814/S	
COUPÉ	HC/782	seat (right/left) HC/818		seat (right) HC/780/D seat (left) HC/780/S		seat (right) HC/822S seat (left) HC/822S	
<b>FORD</b>		<b>MITSUBISHI</b>		<b>IBIZA 3<sup>rd</sup> series &gt;02</b>		<b>POLO 4<sup>th</sup> series 3/5 doors</b>	
KA	seat (right) HC/734/D seat (left) HC/734/S	<b>COLT 3 doors &gt;06/04</b>		seat (right) HC/814/D seat (left) HC/814/S		requires welding seat (right) HC/822D seat (left) HC/822S	
		seat (right) HC/847/D seat (left) HC/847/S		<b>LEON &gt;09/05</b>		seat (right) HC/838/D seat (left) HC/838/S	
		<b>LANCER EVO 6</b>		<b>SMART</b>		<b>YUGO</b>	
		seat (right) HC/803/D seat (left) HC/803/S		<b>SMART &gt;98</b>		<b>KORAL</b>	
		<b>LANCER EVO 7</b>		seat (right) HC/812/D seat (left) HC/812/S		HC/808	
		to be welded to body seat (right) HC/828D seat (left) HC/828S					
		<b>NISSAN</b>					
		<b>MICRA &gt;01/03</b>					
		seat (right) HC/827D seat (left) HC/827S					
		<b>PATROL GR &gt;97</b>					
		seat (right) HC/852D seat (left) HC/852S					